



MINIMUM CLEARANCE REQUIREMENTS



NOTE:

Failure to follow these minimum clearance guidelines may result in the generator failing inspection by the local building, electrical or fire inspector requiring the generator be reinstalled in the correct location.